

SPRING 1976

Monitoring - Pesticides Disposal Sites

Lovelock - Soil (Pershing Co.)

50' North - None

50' East - None

50' South - None

50' West - None

Lovelock - Vegetation

50' North - .002 DDE; .003 H.E.

50' East - None

50' South - .002 DDE; .002 H.E.

50' West - .002 H.E.

Lovelock - Water

(1) Well 1½ miles S.W. - None

(2) Well 2 miles S.W. - None

\*Water in puddles below site after heavy rain - None

Middle Reese - Soil (Lander Co.)

50' North - None

50' East - None

50' South - None

50' West - None

Middle Reese - Vegetation

50' North - None

50' East - None

50' South - None

50' West - None

Middle Reese - Water

(1) Powers Well 2½ miles So. - None

\*Puddles below site after heavy rain - None

Orovada - Soil (Humboldt Co.)

50' North - None

50' East - None

50' South - .003 Aldrin

50' West - .001 Aldrin

Orovada - Vegetation

50' North - .003 DDT

50' East - .009 DDT

50' South - None

50' West - None

Orovada - Water

(1) Spring 1-3/4 miles S.W. - None

(2) Well 2½ miles S.W. - None

\*Runoff puddles below site after heavy rain - None

Monitoring - Pesticides Disposal Sites (Cont'd)

Fallon - Soil (Churchill Co.)

50' North - None  
50' East - None  
50' South - None  
50' West - None

Fallon - Vegetation

50' North - None  
50' East - None  
50' South - None  
50' West - None

Fallon - Water

(1) Well 1 mile East - None

\*H.E. = Heptachlor Epoxide

\*\*Air not monitored at any site

\*\*\*Sites activated 5-15-76 - Samples taken 5-12-76 & 6-10-76